



SAND FENCE UPDATE

#AfterAgnes



Images by

 Galway 
Atlantaquaria® 


SAND DUNE FENCE PHOTO BREACH REPORT

On the 30th of Sept, Dr Kevin Lynch of the Geography Dept University of Galway shared this image of the fence collapse.

After Agnes, there was a lot of Drift Seaweed on Grattan so when the high tide came in it started pushing this mass against the fencing.

This was not a failure of the fencing, rather a series of unfortunate events that culminated/caused this breach.

There was some damage to the flora and embryo dunes, but will not be sure of the extent until the Drift Seaweed gets reabsorbed into the dunes.




**Photo by Dr Kevin Lynch
Geography Dept
University of Galway**

**Time/Date:
18.45 30/10/2023**

















*This is not a disaster the
Dunes are resilient, they will
replenish and come back!*



